

Skid Resistance Testing



TEST REPORT

CLIENT: Pebble-Flex LLC
1 Field Street
Avon by the Sea, NJ
United States 07717

Attn: Gerald M. Saluti

Test Report No: 654:014770-7	Date: August 22, 2008
-------------------------------------	------------------------------

SUBJECT: ASTM C 1028-07 Coefficient of Friction Test.

REFERENCE: Letter.

SAMPLE ID: Three (3) floor tiles identified by client as "Pebble Flex 1" were received from the client on 8/15/08 in good condition.


PROCEDURE: The sample was tested for coefficient of static friction in accordance per ASTM C 1028-07. No revisions to this report will be allowed after 90 days of the report date.


TEST DATE: 8/20/08 - 8/21/08

RESULTS: Results can be found on the following pages.

REMARKS: The Occupational Safety and Health Administration recommend that walking surfaces have a static coefficient of friction of 0.5. According to 28 CFR Ch. 1-1994 Section A4.5.1, a static coefficient of friction of 0.6 is recommended for accessible routes and 0.8 for ramps.

**SIGNED FOR AND ON BEHALF OF
SGS U.S. TESTING COMPANY INC.**


Robert Ross
Materials Technician


S. Scott Parkhurst
Materials Dept. Manager

Page 1 of 2

This report is issued by SGS U.S. Testing Company Inc. under its General Conditions for Testing Services, as printed on reverse side. SGS U.S. Testing's responsibility under this report is limited to proven negligence and will in no case be more than the amount of the testing fees. Except by special arrangement, samples are not retained by SGS U.S. Testing for more than 30 days. The results shown on this test report refer only to the sample(s) tested unless otherwise stated, under the conditions agreed upon. Anyone relying on this report should understand all of the details of the engagement. Neither the name, seals, marks nor insignia of SGS U.S. Testing may be used in any advertising or promotional materials without the prior written approval of SGS U.S. Testing. The test report cannot be reproduced, except in full, without prior written permission of SGS U.S. Testing Company Inc.

SGS U.S. Testing Company Inc. | Consumer Services Division | 1341 North 108th East Avenue, Tulsa, OK 74116 | t (918) 437-8333 | f (918) 437-8487 | www.sgs.com

Member of the SGS Group

Skid Resistance Testing



Client: Pebble-Flex LLC
Report No.: 654:014770-7

ASTM C 1028

Sample ID: Pebble Flex 1

Dry, as Received

	Calibrate	Neolite
Average Force	38.50	39.08
Raw Coeff/Frict	0.75	0.76
Correction	0.11	0.11
Cor. Coeff/Frict.	0.86	0.87

Wet, as Received

	Calibrate	Neolite
Average Force	24.75	37.08
Raw Coeff/Frict	0.48	0.73
Correction	0.03	0.03
Cor. Coeff/Frict.	0.51	0.75

Dry, as Renovated

	Calibrate	Neolite
Average Force	39.25	40.25
Raw Coeff/Frict	0.77	0.79
Correction	0.09	0.09
Cor. Coeff/Frict.	0.86	0.88

Wet, as Renovated

	Calibrate	Neolite
Average Force	27.25	42.33
Raw Coeff/Frict	0.53	0.83
Correction	-0.02	-0.02
Cor. Coeff/Frict.	0.51	0.80

End of Report